

10/500083

1/24

Fig. 1






Fig. 2



3/24

Fig. 3



4/24

REHABILITATION ROOM




Fig. 4

5/24





Fig. 5

6/24

Fig. 6



7/24

Fig. 7

PLACE	EXAMPLE OF COMBINATION OF BEHAVIOR DETECTING MEANS		DETECTED BEHAVIOR
	BEHAVIOR DETECTING MEANS 1	BEHAVIOR DETECTING MEANS 2	
REHABILITATION ROOM	LOAD SENSOR (PARALLEL BARS)	LOAD SENSOR (PARALLEL BARS)	WALK
TOILET	DOOR OPEN/CLOSE SENSOR	LOAD SENSOR (TOILET SEAT)	WALK
CORRIDOR	PASSAGE DETECTION SENSOR	PASSAGE DETECTION SENSOR	WALK
CORRIDOR	LOAD SENSOR (HAND RAIL)	LOAD SENSOR (HAND RAIL)	WALK
TOILET	LOAD SENSOR (TOILET SEAT)	DOOR OPEN/CLOSE SENSOR	WALK
STAIRCASE	PASSAGE DETECTION SENSOR (LOWERMOST STEP)	PASSAGE DETECTION SENSOR (UPPERMOST STEP)	WALK

8/24





Fig. 8

9/24

Fig. 9



10/500083

10/24

Fig. 10 (a)





Fig. 10 (b)



11/24

Fig. 11




Fig. 12 (a)

JUST AFTER OPERATION




Fig. 12 (b)

TEN DAYS AFTER OPERATION





Fig. 13



14/24





Fig. 14


15/24

Fig. 15



16/24

Fig. 16



10/500083

17/24




Fig. 17

Best Available Copy

18/24

Fig. 18




Fig. 19 (b)




Fig. 19 (a)





Fig. 20 (b)

RANGE OF INTEGRATED VALUES	RANK
20000-22000	10
22001-24000	11
24001-26000	12
26001-28000	13

Fig. 20 (a)



10/500083

21/24




Fig. 21

107500083

22/24




Fig. 22

Best Available Copy

23/24




Fig. 23

Fig. 24 (a)




Fig. 24 (b)




Fig. 24 (c)

